

60 Webro Road, Clifton, NJ 07012 Tel: 973-614-9000 www.DriTac.com

Technical Bulletin 2-1-1

<u>SUBJECT</u>: EnStron Underlayment resilient floor underlayment by Plummer Forest Products

DriTac Flooring Products warrants the use of the following flooring adhesives to install approved resilient flooring over properly prepared EnStron Underlayment resilient floor underlayment.

- DriTac 5900 MegaBond Premium "Green" Pressure Sensitive Resilient Flooring Adhesive
- DriTac 5800 ToughBond Premium "Green" Pressure Sensitive Resilient Flooring Adhesive
- DriTac 5700 StrongBond Premium"Green" Pressure Sensitive Resilient Flooring Adhesive

DriTac also warrants the use of the following flooring adhesives to install approved wood flooring over properly prepared EnStron Underlayment resilient floor underlayment.

- DriTac 7800 Supreme Green Premium "Green" Sound and Moisture Control Hybrid Polymer Wood Flooring Adhesive
- DriTac 4141 Golden Bullet Premium "Green" Sound and Moisture Control Urethane Wood Flooring Adhesive
- DriTac 7700 Easy Clean Premium "Green" Sound and Moisture Control Modified-Silane Polymer Wood Flooring Adhesive
- DriTac 7300 SureBond Urethane Wood Flooring Adhesive

This is all subject to our standard product warranties.

All DriTac flooring adhesives and Plummer Forest Products' EnStron Underlayment resilient floor underlayment must be installed according to each individual product specifications. Not following these recommendations will void this warranty.

The success or failure of any installation using our adhesives and any flooring system cannot be determined based solely on lab test results. The requirements and installation instructions of DriTac Flooring Products and the flooring manufacturer must be followed, including but not limited to flatness of the concrete subfloor (level of plane), concrete moisture content, acclimation of the flooring, proper climate control, use of the correct trowel, proper flash time of the adhesive and all other relevant jobsite conditions as specified by all manufacturers involved.

FOR FURTHER INFORMATION – Contact DriTac Technical Services Department at (973) 614-9000 or e-mail us at info@DriTac.com.